

INFORMATION ONLY

ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE HEALTH AND SAFETY PLAN ACCIDENT PREVENTION SAFETY PROGRAM PLAN INT OPER. UNITS	Manual No.: Section No. Page: Effective Date: Organization:	RFP/ERM-94-00019 Table of Contents, R1 1 of 1 1/12/95 Environmental Restoration Mgmt
--	---	--

TABLE OF CONTENTS HEALTH AND SAFETY PLAN ACCIDENT PREVENTION SAFETY PROGRAM PLAN INTEGRATED OPERABLE UNITS

<u>Section No.</u>	<u>Title</u>	<u>Rev. No.</u>	<u>Effective Date</u>
	Detailed Table of Contents	0	11/04/94
•95-DMR-ERM-0004	Personnel and Site Condition Changes to OU9 Affects sections 2,5,6,7,8,9,10,APPC	0	1/12/95
1 0	Introduction	0	11/04/94
2 0	Health and Safety Personnel	0	11/04/94
3 0	Facility Characteristics	0	11/04/94
4 0	General Health and Safety Requirements	0	11/04/94
5 0	Hazard Evaluation	0	11/04/94
6 0	Personnel and Air Monitoring	0	11/04/94
7 0	Work Zone	0	11/04/94
8 0	Personal Protective Equipment	0	11/04/94
9 0	Decontamination Procedures	0	11/04/94
10 0	Emergency Response Plan	0	11/04/94
11 0	Logs, Reports, and Record Keeping	0	11/04/94
12 0	References	0	11/04/94
APPA	Appendix A Personal Protective Equipment and Monitoring Requirements	0	11/04/94
APPB	Appendix B Jacobs' Medical Surveillance Procedures	0	11/04/94
APPC	Appendix C Jacobs Engineering Group Standard Operating Procedures	0	11/04/94

ADMIN AND

DOCUMENT CLASSIFICATION
PER RB HOFFMAN, CLASS
JUNE 11 1995

A-OU09-000165

INFORMATION DOCUMENT MODIFICATION REQUEST (DMR)

95-AMR-

Page 1 of 3

Refer to 1-A01-PL for Processing Instructions
Print or Type All Information (Except Signatures)

Existing Document Number/Revision RFP/ERM-94-00019			1 Date 12/9/94		25 DMR No 94-DMR <i>ERM-0004</i> <i>Am 1/9/95</i>	
4 Originator's Name/Phone/Page/Location <i>James Peterson 9659/5472/080</i>			3 New Document Number or Document Number if it is to be changed with this Revision N/A			
6 Document Type <input type="checkbox"/> Procedure <input checked="" type="checkbox"/> Other <i>H&S Plan</i>			5 Document Title Integrated Operable Units Health & Safety Plan			
7 Document Modification Type (Check only one) <input type="checkbox"/> New <input type="checkbox"/> Revision <input type="checkbox"/> Intent Change <input checked="" type="checkbox"/> Nonintent Change <input type="checkbox"/> Editorial Correction <input type="checkbox"/> Cancellation						
8 Item	9 Page	10 Step	11 Proposed Modifications			
1	2-2	F2-1	Change names as shown on revised F2-1 OU9 Project Manager is John Zimmerman, Field Team Leader is Simon Bell, H&S Coordinator is Lisa Nelowet OU14 Project Manager is Bill Fieselman, HSS's are David Spruce, Tom Waddei			
2	Sec 6 p 4	6 3	Delete 1st two sentences of Personal Sampling paragraph Modify third sentence to read as follows "Personal sampling will be conducted only when Level C action Levels are reached with direct reading instruments or when otherwise noted in Appendix A "			
3	Sec 6 p 7	6 4 4	Insert new first sentence "Personal sampling will only be performed when directed to by EG&G Radiological Engineering "			
4	Sec 6 p 8	6 4 6	Insert new first sentence "Ambient air sampling for airborne alpha radioactivity will only be performed when directed to by EG&G Radiological Engineering or if action levels for dust are exceeded in an RCA			
5	Sec 5 p 42	5 5 9 1	Delete the word "strenuous" from the first sentence of "Heat Stress Monitoring and Work Cycle management " Delete "even if workers are not wearing impervious clothing " Delete "and body water loss" from 2nd paragraph under "Heat Stress Monitoring " Change "oral temperature" to "oral or ear canal temperature "			
6	Sec 6 p 3	6 3	Delete paragraph 6, " The fact that contaminants are listed "			
12 Justification (Reason for Modification EJO# TP# etc) Incorporating changes to improve compliance with 29CFR1910 120 and reflect current personnel and site conditions						
If modification is for a new procedure or a revision list concurring disciplines in Block 13 and enter N/A in Blocks 14 and 15 If modification is for any type of change or a cancellation organizations are listed in Block 13 then Concurcor prints and signs in Block 14 and dates in Block 15						
13 Organization	14 Print and Sign (if applicable)				15 Date (if applicable)	
EOM	K D Anderson <i>[Signature]</i>				12/22/94	
RE	D Hyder <i>[Signature]</i>				12/22/94	
IH	M D Schreckengast <i>[Signature]</i>				1/2 --	
IA OU	B D Peterman <i>[Signature]</i>				12/20/94	
QA	R. S. LUTER <i>[Signature]</i>				1/9/95	
16 Originator's Supervisor (print/sign/date) Bruce D Peterman <i>[Signature]</i> B.D Peterman 12/22/94						
17 Assigned SME/Phone/Page/Location Craig Cowdery/6953/5466/080		18 Cost Center 3113		19 Charge Number 98903600		20 Requested Completion Date 1/1/95
21 Effective Date 1/12/95						
22 Accelerated Review? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>		23 ORC Review N/A				
4 Responsible Manager (print/sign/date) Craig Cowdery <i>[Signature]</i> 12/22/94						

Received for Dist. at 3:40 1/9/95

REVIEWED FOR CLASSIFICATION/UCN
BY NA
DATE NA

Refer to 1-A01-PPG-001 for Processing Instructions
Print or Type All Information (Except Signatures)

25
DMR No 95-DMR-ERM-0004
94 DMR
Jan 1/9/95

2 or 3 Document Number/Revision RFP/ERM 94-00019			3 Document Title Integrated Operable Units Health & Safety Plan
8 Item	9 Page	10 Step	11 Proposed Modifications
7	Sec 9 p 2	9 1 1	Change "dispose of glove" to "dispose of outer gloves" Add bullet after "Remove respirator bullet" to read "Remove and dispose of inner gloves "
8	Sec 8 p 2	8 1 1	Change first paragraph to read "For activities to be conducted under this plan, personnel will wear Level D as defined in Section 8 1 3 " Delete paragraphs 2 and 3
9	Sec 8 p 5	8 1 3	Add bullet after dosimeter badge bullet to read "nitrile gloves if hand contact with potentially contaminated materials is likely "
10	Sec 5 p 14	5 2 2	Integrate new chemicals as shown into Section 5 2 2 alphabetically
11	Sec 5 p 2	5 2 Table 5-1	Integrate new chemicals as shown into Table 5-1 chemical Exposure Hazard Summary alphabetically
12	Sec 5 p 38	5 5 3	Change "Utility clearance will be completed before work begins " to "Utility clearance will be completed by the client before work begins "
13	Sec 5 p 38	5 5 3	Change (SOP 7 7) to read SOP 7 7a
14	Sec 5 p 38	5 5 3	Delete "which uses hand-augering to confirm the absence of buried utilities," Change the last sentence to read "A copy of Jacobs' SOP 7 7a is provided in Appendix C
15	Appendix C	SOP 7 7	Delete SOP 7 7, add new SOP 7 7a Utility Clearance at Rocky Flats Plan (7 pages)
16	Sec 7 p 4	7 1 5	The fourth bullet will read as follows "All visitors will receive a site specific safety briefing, and will be escorted at all times Visitors in areas requiring Level A B or C PPE must have the equivalent training and PPE as the onsite worker to gain entry "
17	Sec 7 p 4	7 1 5	Add bullet after above statement that reads, "Visitors in areas requiring Level D PPE must have Level D PPE, receive a site specific safety briefing, and will be escorted at all times
18	Sec 7 p 4	7 1 5	Add paragraph/sentence after "All site visitor access must be clearly documented " bullet to read "If visitor does not supply current documentation but insists that he/she enters area the following actions are to be taken "
19	Sec 7 p 4	7 1 5	Add bullet after above new statement to read On site HSS or HSST will shut down activities, secure area by monitoring with instrumentation, and contact HSO/HSS or Site Manager
20	Sec 7 pg 5	7 2	Is first sentence delete "heavy equipment or"
21	Sec 6 p 4	6 3	Add new text to end of <u>Action Levels</u> paragraph <u>When</u> action levels are reached which, according to Appendix A, require "evacuation and reevaluation," site workers must move to an area where direct reading instrumentation shows airborne concentrations are below the action levels of concern The HSS/HSST must contact the Health & Safety Coordinator to determine further action

Refer to 1-A01-PPG-001 for Processing Instructions
Print or Type All Information (Except Signatures)

25 95-DMR-ERM-0004
DMR No. ~~94-DMR~~ Jan 1/9/95

or 3 Document Number/Revision
RFP/ERM-94-00019

3 Document Title
Integrated Operable Units Health & Safety Plan

8 Item	9 Page	10 Step	11 Proposed Modifications
22	Sec 6 p 2	6 3	Add to end of 1st paragraph "All monitoring will be in the breathing zone unless otherwise specified in Appendix A "
23	Sec 10 p 2	10 2 1	Add EG&G Operations Manager Representative Change "Kent Mahana" to "Lisa Nelowet "
24	Sec 10 p 3	10 2 1	Add EG&G Operations Manager Representative
25	Sec 10 p 8	10 3 1	Add Operations Manager Representative, as listed in Tables 10-1, 10-2, must be notified of any unplanned releases
26	Sec 10 p 9	10 3 2	Change "Kent Mahana" to "Lisa Nelowet"
27	Sec 5 p 5-31	T5-4	Modify as shown
28	Sec 6 p 3	6 3	Replace "every 15 minutes" to "whenever site conditions change" in first paragraph
29		F7-1	Delete figure
30	Sec 7 p 5	7 2 1	Delete 1st sentence
12 Justification (Reason for Modification EJO# TP# etc)			

TABLE OF CONTENTS

(Continued)

	Page
10.4.4 First-Aid Register	10-11
10.4.5 Vehicle Accident Reporting Procedure	10-11
10.5 ROCKY FLATS PLANT REPORTING PROCEDURE	10-11
11.0 LOGS, REPORTS, AND RECORD KEEPING	11-1
11.1 HEALTH AND SAFETY LOGBOOK	11-1
11.2 CALIBRATION LOGS	11-1
12.0 REFERENCES	12-1

List of Figures

Figure 2-1	Integrated OU Project Organization Chart Rocky Flats Plant	2-2
Figure 3-1	Rocky Flats Plant - Location Map	3-2
Figure 3-2	Rocky Flats Plant - General Map	3-3
Figure 3-3	Rocky Flats Plant Building Location Map	3-5
Figure 7-1	Typical Site Control Layout	7-6

List of Tables

Table 3-1	Summary of Nonintrusive Activities by Integrated Operable Units and Individual Hazardous Substance Sites	3-10
Table 5-1	Chemical Exposure Hazard Summary	5-2
Table 5-2	Integrated Operable Unit Location and Hazard Summary by Individual Hazardous Substance Site	5-4
Table 5-3	Radionuclides	5-12
Table 5-4	Asphalt and Concrete Removal and Sampling	5-31
Table 5-5	Polychlorinated Biphenyl Sampling	5-32

TABLE OF CONTENTS

(Continued)

	Page
Table 5-6 Polychlorinated Biphenyl Sampling	5-33
Table 5-7 Soil-Gas Survey	5-35
Table 5-8 Surface Water and Sediment Sampling	5-36
Table 6-1 Survey Instrumentation	6-6
Table 9-1 Radioactive Contamination Limits	9-3
Table 10-1 Emergency Telephone Numbers - Fieldwork	10-2
Table 10-2 Pager Numbers	10-3

List of Appendices

APPENDIX A Personal Protective Equipment and Monitoring Requirements

APPENDIX B Jacobs' Medical Surveillance Procedures

APPENDIX C Jacobs Engineering Group Standard Operating Procedures

LIST OF EFFECTIVE PAGES

<u>Pages</u>	<u>Effective Pages</u>	<u>Change Number</u>
TOC viii	1/12/95	95-DMR-ERM-0004
Section 5. 1-59	1/12/95	95-DMR-ERM-0004
Section 6. 2-4, 7-8	1/12/95	95-DMR-ERM-0004
Section 7: 4-5	1/12/95	95-DMR-ERM-0004
Section 8. 2, 5	1/12/95	95-DMR-ERM-0004
Section 9. 2	1/12/95	95-DMR-ERM-0004
Section 10. 2-3, 8-9	1/12/95	95-DMR-ERM-0004
Appendix C: SOP 77a	1/12/95	95-DMR-ERM-0004

recorded includes type of instrument, manufacturer and serial number, calibration standard used and lot number or other unique identifier, initial readings, adjustments made, and final reading. A copy of Jacobs' instrument calibration form is included in Appendix C.

- 2 Calibration standards will be traceable to a National Institute of Standards and Technology primary standard or be a recognized primary standard. Copies of calibration standard certificates will be maintained at the project site.

6.3 AMBIENT AIR AND PERSONAL MONITORING

Ambient air monitoring and personal sampling will be conducted during activities covered by the HSP. This monitoring will be used to document employee exposure and provide a reference for future activities. All monitoring will be in the breathing zone unless otherwise specified in Appendix A.

Ambient Monitoring Methods Ambient air monitoring for nonradioactive contaminants will be conducted for activities covered by this plan using calorimetric tubes, a photoionization detector (PID), and a real-time dust monitor.

A PID using an 11.7 electron volt (eV) lamp in the total response mode will be used to monitor sites as presented in Appendix A. Upon arrival at a work site, the PID will be zeroed relative to ultra zero air. After the PID has been zeroed, a background reading will be taken upwind of the work site. Additional measurements will be taken at the work site with each soil or soil-gas sample collected. If an action level, as defined in Appendix A, is reached, readings will be monitored continuously. Background readings will be repeated whenever weather or wind direction changes. A sustained reading in the breathing zone is defined here as a reading measured using the PID where air is being inhaled over a five-minute interval.

95-DMR-ERM-0004
Colorimetric tubes will be used at each IHSS, as outlined in Appendix A, after an action level is reached with real-time instrumentation or if free liquids are observed. When colorimetric tubes are required, an upwind sample will be collected for each contaminant and be recorded as the background. Additional measurements will be obtained at the work site with each soil sample collected. If an action level is reached, additional measurements will be taken whenever site conditions change. Background measurements will be repeated if weather conditions or wind direction change. If no compounds are detected by photoionization, and personal sampling results provide no indication of overexposure, colorimetric tubes will not be used.

Real-time dust monitoring will be conducted at all work sites to determine background particulate levels and monitor particulate resuspension as work is conducted. Readings will be measured at the worker breathing zone. Many particulate contaminants at individual IHSSs are designated to be monitored by a real-time aerosol monitor (MIE Mini-ram) in Appendix A. Action levels for dust monitoring are based on a nuisance dust standard of 10 mg/m³. For Level D activities, concentrations of 25 percent of the standard (2.5 mg/m³) are allowed, up to 50 percent (less than 5 mg/m³) for Level C, and for concentrations in excess of 50 percent (>5 mg/m³) Level B will be used. Action levels are based on the average concentration obtained during a five-minute sampling period. Upon arrival at a site, a background reading will be obtained from an upwind location. Additional measurements will be collected upon arrival at the work site and with each sample taken during sampling activities. If an action level is reached, readings will be measured continuously.

Action Levels for Suspect Contaminants Action levels for nonradioactive contaminants are established by individual IHSS and documented in Appendix A. In setting the levels for which contaminants are known and for which specific monitoring methods are available, the PEL or ACGIH threshold limit value (TLV) for a contaminant was used as the action level for Level C protection. Maximum use concentrations for Level C work were determined by multiplying the action level by a respiratory protection factor. A conservative factor of 10 was used for full-face respirators. Additional considerations include availability and service limits of air-purifying cartridges for a given contaminant. Where cartridges are unavailable or contaminant levels exceed service limits, demobilization or transition from Level D modified to Level B will be required.

When action levels are reached which, according to Appendix A, require "evacuation and reevaluation," site workers must move to an area where direct reading instrumentation shows airborne concentrations are below the action levels of concern. The HSS/HSST must contact the Health & Safety Coordinator to determine further action.

Documentation All monitoring results and other pertinent actions will be recorded in the Health and Safety Officer's field logbook. In addition, each instrument's name, model, serial number, and site conditions will be recorded once before the first entry of monitoring results.

Personal Sampling Personal sampling will be conducted only when Level C action levels are reached with direct reading instruments or when otherwise noted in Appendix A. Sampling results will be used to determine personnel exposure and revise monitoring requirements. Where mixtures of chemicals are detected, the computational formula for mixed contaminants will be used to assess exposure. Where results indicate no detected overexposure, sampling will be discontinued for that contaminant. An action level of 50 percent of the TWA.

Table 6-1
Survey Instrumentation

Instrument	Target Radiation
Ludlum 12-1A with Air Proportional Probe	Alpha Contamination
Ludlum 31 or 12 Count Rate Meter with Pancake Detector, 44-9 Probe	Beta/Gamma

As covered by the EMRG, the front and back, feet, and boots of personnel will be monitored by moving the detectors over outer clothing and exposed skin areas at a rate not to exceed 2 inches per second. Clothing contaminated with radioactivity exceeding 300 disintegrations per minute (dpm)/100 cm² alpha (detected by Ludlum 12-1A) or 100 cpm/beta gamma above background (detected by Ludlum 31/12) will be considered contaminated.

In the event that personnel contamination is detected, field decontamination will be attempted as outlined in Section 9.1, Personnel Decontamination. If contamination is detected, Jacobs' personnel will maintain the site zone boundaries and notify the ERHSO, EG&G Radiological Engineering, and EG&G Contractor's Technical Representative. All radiological occurrences will be documented in accordance with EMRG 10.1, Radiological Deficiency Reporting Program.

6.4.4 Personal Sampling for Airborne Activity

Personal sampling will only be performed when directed to by EG&G Radiological Engineering Representative. Personal sampling from each field team working in radiologically contaminated areas (greater than or equal to 25 percent of personnel) will be conducted for airborne alpha radioactivity using Jacobs' Radiological Operations Procedure (ROP) 10.02, Personal Air Particulate Sampling. A type A-E, glass fiber filter will be used to collect airborne particulates. At the end of the shift, the filter will be removed and counted in accordance with Jacobs ROP 10.03, Performance Check and Operation of Alpha Smear/Filter Counting Instrumentation. The

resulting data will be compared with the derived air concentration that is the most conservative for the contaminants suspected of being present to gauge employee exposure. Derived air concentrations for suspect contaminants are given in DOE 5480 11. Sampling results equal to or greater than 10 percent of the Derived Air Concentration (DAC) will be reported to the ERHSO. After the first five samples are analyzed, a review of the data will be conducted to make a determination whether to continue to monitor for airborne alpha radioactivity. If the levels are below the guidelines stated in Jacobs' ROP 10 02, the monitoring will be discontinued.

6.4.5 External Dosimetry

Jacobs' employees and subcontractors will participate in the EG&G Rocky Flats External Dosimetry Program as outlined in HSP 18 07, External Radiation Dosimetry. Jacobs' personnel will wear EG&G-supplied thermoluminescent dosimeters while in the field to assess beta, gamma, neutron, and X-ray exposure while working at Rocky Flats. When not in use, they will be kept on a board within the support trailers. Dosimeters will be exchanged quarterly.

6.4.6 Ambient Air Monitoring for Radionuclides

Ambient air sampling for airborne alpha radioactivity will only be performed when directed to by EG&G Radiological Engineering, or if dust action levels are exceeded in an RCA. Ambient air sampling for airborne alpha radioactivity will be conducted when required with high-volume air samplers using Jacobs' ROP 10 01, High Volume Air Particulate Sampling. Samples will be counted in accordance with Jacobs' ROP 10 03. Grab samples will be collected in the immediate vicinity of work being performed during each shift to determine 1) whether the area is an airborne radioactivity area requiring additional work controls and 2) if personal breathing-zone air sampling is necessary to assess the worker's intake of airborne radioactive materials. In accordance with the protocol for personal sampling in Section 6 4 4, high-volume sample results will be compared with the most conservative derived air concentrations given in DOE 5480 11, and results greater than 10 percent DAC will be reported to the ERHSO. Depending on adjacent IHSS logistics, radionuclide air monitoring locations may be chosen to represent more than one IHSS.